

# Form for risk analysis - Brushcutter



Sources of danger/ identified risk	Likelihood of injury  S	Consequence of injury? What can happen?  K	Risk  S x K	What can be done to reduce the consequences? Preventive actions	Risk after action  S x K
Filling of fuel	Likely - 3	Critical/serious - 3 Singe and burn injury	3 x 3  9	Use funnel on the can. Wear gloves. Turn your face away from the "steam"	1 x 2  2
Replacement of equipment, blades / driver	Slightly likely - 2	Slightly serious - 2 Cut injury	2 x 2  2	Use gloves and suited equipment	1 x 1  1
By thinning; blades Fall of trees; branches	Slightly likely - 2	Slightly serious - 2	2 x 2  4	Use a helmet with visor and glasses. Safety zone about 5 meters.	1 x 2  2
Ergonomics	Likely - 3	Critical/serious - 3 Abrasion	3 x 3  9	Correct setting of harness and saw. Good footwear, good balance.	1 x 2  2

<b>Participated:</b>	<b>Signature:</b>	<b>Date:</b>